

CDSERAL CONSTRUCTION NOTES:

1. DISTURBED SCILS SHOULD BE STABILIZED AS SOON AS
POSSIREL RECOURTE MEASURES SHOULD BE TAKEN TO
PREVENT EROSION AND TO CONTAIN SERVICINT ON SITE
EROSION CONTROLS SUCH AS SLIT FENENCH HAYBLES, AND
SWEEPING SHOULD BE USED AS RECESSARY.

- 2. THE CONTRACTOR SHALL COORDINATE INSPECTIONS OF THE SUBSURFACE DRAINAGE SYSTEM WITH THE TOWN OF ARLYIGTON ENGINEERING DEPT. PRIOR TO BACKFILLING.
- 3. THE PROPOSED CURB CUT AND SICEWALK CONSTRUCTION SHOULD BE COORDINATED WITH TOWN OF ARUNGTONE STRUCTURE BOTH. AND BOILT BE COMPULATED WITH THE TOWN OF ARRINGTON STRUDARD DRIVEWAY CROSSING AND SIERWALK DETAILS.
- 4. ALL WALLS GREATER THAN 4" IN HEIGHT SHALL BE DESIGNED BY A REGISTERED STRUCTURAL ENGINEER PRIOR TO CONSTRUCTION.
- 5. FALL PROTECTION AND HANDRAILS SHALL BE PROMDED AS REQUIRED BY BUILDING CODE OR OTHER APPLICABLE CODE(S) OR REGULATION(S), AND SHALL BE APPROVED BY THE DWINER PRIOR TO INSTALLATION.
- 6. SITE GRADING AND DOWNSFOUT OVERFLOWS SHALL NOT DRECT CONCENTRATED STORMWATER RUNOFF ONTO ABUTTING PROPERTIES.
- 7. THE CONTRACTOR SHOULD MONITOR AREAS OF EXPOSED SOIL TO INSURE THAT ENOSON IS KEPT TO A MINIMUM AND SEDMENT IS CONTAINED CH-STE. ANY ESHIDATE DITERING THE RIGHT OF WAY SHOULD BE REMOVED INVESTMENT, RADEWAY STREET SWEEPING AND/OR CLEARING SHOULD TAKE PLACE AT THE END OF EACH WORK DAY.
- 8. A FELD AS-BULT PLAN OF THE DRAINAGE SYSTEM AND INFERMIOUS AREAS (W/ DIMENSIONS) SHALL BE PROMEED TO THE ARLINGTON ENGINEERING CEPT. FOLLOWING INSTALLATION.
- 9. ANY FROPOSED AND/OR FUTURE SUMP PUMP INSTALLATION SHOULD NOT BE DISCHARGED TOWARDS THE PUBLIC WAY OR CONNECTED TO THE SUBSURFACE RECHARGE SYSTEM.
- 10. FOOTING DRAIN OUTFALLS SHALL NOT BE DEFECTED TOWARDS ABUTTING PROFERITES
- 11. THE CONTRACTOR SHALL COORDINATE THE FOLLOWING INSPECTIONS OF SUBSURFACE DRAINAGE SYSTEM WITH THE TOWN OF ARIJINATION ENGINEERING OPP.: (A.) THE BOTTOM OF EXCAVATION (E.) SYSTEM INSPECTION AFTER INSTALLATION AND FROR
- 12. THE INFLITRATION SYSTEM'S BOTTOM OF RED SHALL BE EXCAVATED TO THE C HORAZON SCIL LAYER, IF UNSUITABLE SOIL CONDINORS ARE ENCOUNTERED, (IE LEDGE, FILL, LACK OF SOIL DEPTH, ETC.) THE CONTRACTOR SHAULD CONTRACT THE DESIGNER AND ENGINEERING DIMSION.

CHESTAL UTLITY MOTES

IN THE LOCATION OF DISTRIBUTES INCLORNO
PIPES, CONDUTS, WARRIES, POLES, AND OTHER
POLITY FRANKES AS SHOWN ON THESE FLASS ASE
NOT WARRANTED TO BE COORECT ON COMPLETE.

WARRANTED TO BE COORECT ON COMPLETE.

OR THE CONTROL OF THE CONTROL OF THE CONTROL

OR THE CONTROL OF THE CONTROL OF THE CONTROL

OR THE CONTROL OF THE CONTROL OF THE CONTROL


OR THE CONTROL OF THE CONTROL OF THE CONTROL

OR THE CONTROL OF THE CONTROL OF THE CONTROL


OR THE CONTROL OF THE CONTROL

2. INSTALLATION OF UTILITIES SHALL CONFORM TO ALL APPLICABLE REGULATIONS, CODES, AND STANDARDS, NOLLEWING THOSE OF THE CITY OF ARUNGTON.

3. This plan provides information for exterior utilities only. Utilities inside the building to be designed and specified by others.




SILT FENCE DETAIL



TYPICAL RECHARGE AREA

MOTE: 1. RECHARGE SYSTEM CONSISTS OF (3) THREE 330XL HD CULTEC CHAMBERS.

> N/F MICHAEL FAIOLA, TRUSTEE OF FAIOLA REALTY TRUST



MASSACHUSETTS (PUBLIC - 76.00' WIDE) AVENUE

SCALE: 1'=10'

Lot Coverage Summary Existing: 1,572 sf Bldg. Dwy & Walks 4,624 sf Total: 6,196 sf Proposed: Bldg. 3,180 sf Dwy's & Walks 2,416 sf Total: 5,596 sf Net Change: - 600 sf

WID

9

40.

(PUBLIC

STORMWATER MANAGEMENT
SITE PLAN
SITE

90 PINE STREET

(978)204-2390

DANVERS, MA 01923

DATE MAY 2, 2017

8CALB 7-10"

PROTECT STATES OF THE STATES OF STAT

EG J ME

Operation and Maintenance Plan

This Stormwater Operation and Maintenance Plan covers the post-construction operation and maintenance of the stormwater management system for 887 Massachustts Ave. in Arlington, Massachusetts. The procedures, practices, and schedule outlined in this plan are intended to be ongoing requirements and are an important factor in ensuring the continued proper functioning of the stormwater management system and integrity of the discharged stormwater.

The following maintenance requirements are the sole responsibility of the property owner(s) and/or the properties home owners association.

Recharge Systems (Chambers)

- Inspect systems after every major storm in the first three months of construction to ensure proper stabilization and function. Thereafter, inspect quarterly.
- Clean systems at least once per year, or more frequently, as needed to prevent accumulation of sediment and other debris in the system.
- Remove leaf litter and other debris from gutters and downspouts as needed to ensure adequate capacity for collection of runoff.
- Clean chambers when debris and or sediment has accumulated to a depth of inches.